

DECONTROLLED/UNCLASSIFIED

LIMITED OFFICIAL USE

Date Printed: 06/24/1998

DOC\_NUMBER: 94STATE222892

RELEASED IN FULL: 2: E261

LIMITED OFFICIAL USE

PAGE 01 STATE 222892 182313Z  
ORIGIN AF-01

INFO	LOG-00	AID-01	CIAE-00	SMEC-00	OASY-00	DOEE-00	EB-01
	EUR-01	OIGO-01	H-01	INM-02	TEDE-00	INR-00	IO-16
	L-01	ADS-00	NSAE-00	NSCE-00	OIC-02	OMB-01	PA-01
	PM-00	PRS-01	P-01	SB-00	SNP-00	SP-00	SR-00
	SS-00	STR-01	TRSE-00	T-00	USIE-00	SNIS-00	NISC-02
	PMB-00	PRM-10	PRME-01	DRL-09	G-00	/054R	

DRAFTED BY: AF/RA:AMARLEY:TCW

APPROVED BY: AF/RA:LSHURTLEFF

AF/C:MGRANDFIELD

AF/C:DRAWSON

-----6960C6 182314Z /38

P 182313Z AUG 94

FM SECSTATE WASHDC

TO AMEMBASSY NAIROBI PRIORITY

AMEMBASSY DAR ES SALAAM PRIORITY

AMEMBASSY KAMPALA PRIORITY KINSHASA PRIORITY

AMEMBASSY ADDIS ABABA PRIORITY

AMEMBASSY LONDON PRIORITY

AMEMBASSY PARIS PRIORITY

AMEMBASSY ROME PRIORITY

USEU BRUSSELS PRIORITY

USMISSION GENEVA PRIORITY

USMISSION USUN NEW YORK PRIORITY

SECDEF WASHDC//SOLIC:HRA//PRIORITY 4366

JOINT STAFF WASHDC//J-3/J-4/J-5//PRIORITY 1032

DLA CAMERA STA VA PROITY

USCNC TANS SCOTT AFB IL PROIY

CNCUSACOM NORFOLK VA PROIITY

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 STATE 222892 182313Z  
USCINCTRANSCOM SCOTT AFB IL/TCJ3/J4-OD/J8/CAT//PR  
USCNCEUR VAHNGEN GE//ECJ3/J4/J5//PROIY  
CNCUSAREUR HEDELBERG GE//AFAGE- 0//PRIORTY  
CNCUSAFE RAMSTEN AB GE//CC//DO/DOX/RS//PROITY  
CNCUSNAVEUR LONDON UK//N3/M31/N5/N7//PROIITY  
COMSOCEUR VAHNGEN GE PROITY  
USCNCCENTMMACDILL AFB FL//CCJ3//PROITY  
SECDEF WASHDC//OASD(SOLC) HRA-OPS//PROITY  
JOINT STAFF WASHDC//J4:LRC/J5:MEAF//PROITY

LIMITED OFFICIAL USE STATE 222892

E.O. 12356: N/A

UNITED STATES DEPARTMENT OF STATE

TAGS: PREF, PREL, PHUM, EAID, MOPS, RW REVIEW

SUBJECT: KIGALI/KAMPALA ROAD INFO

AUTHORITY: EDWARD W. HOLMES

Page - 1  
DECONTROLLED/UNCLASSIFIED

Date Printed: 06/24/1998

DOC\_NUMBER: 94STATE222892

CHANNEL: n/a

2:

1. SUMMARY. EMBOFF DROVE FROM KIGALI TO KAMPALA AUGUST 8 AND FOUND THE ROAD IN GENERALLY GOOD CONDITION. TRIP TOOK SIX AND A HALF HOURS. ONLY IMPEDIMENT TO CARGO TRANSPORT BY ROAD IS A BRIDGE AT THE BORDER WHICH NEEDS TO BE REPLACED. END SUMMARY.

2. AF/RA LTCOL MARLEY, CURRENTLY ON TDY AT EMBASSY KIGALI, DROVE AUGUST 8 FROM KIGALI TO KAMPALA AND FOUND THAT THE ROAD CONDITIONS ARE GENERALLY GOOD. THE FOLLOWING ARE HIS OBSERVATIONS AS REPORTED IN TELCON TO AF/C.

3. THE ENTIRE TRIP TOOK SIX AND A HALF HOURS FROM EMBASSY KIGALI TO EMBASSY KAMPALA, INCLUDING ABOUT 30 MINUTES OF  
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 03 STATE 222892 182313Z  
CITY TRAFFIC UPON ARRIVAL IN KAMPALA. ROAD IS TWO LANES, PAVED, AND IN MOST PLACES IS IN EXCELLENT CONDITION. IN ABOUT 12 - 15 SPOTS AT VARIOUS POINTS ON THE ROAD, ROCK SLIDES HAVE BLOCKED OFF PART OF ONE LANE (ABOUT ONE THIRD OR ONE HALF OF THE LANE), BUT THERE IS SPACE FOR TRUCKS TO GET BY. THE CRATER WHICH WAS BLOWN INTO THE ROAD IN 1990

AT A LOCATION 62 KM. FROM KIGALI HAS BEEN FILLED WITH LATERITE AND DOES NOT IMPEDE TRAFFIC FLOW.

4. ROUGH AREAS: THERE ARE THREE ROUGH AREAS WHERE PAVEMENT HAS DETERIORATED. 1) BETWEEN KM. 64 AND 65, THE ROAD IS HEAVILY POTHOLED. 2) THERE IS A ONE KILOMETER STRETCH BETWEEN KM. 68 AND 69 WHICH APPEARS NEVER TO HAVE BEEN PAVED. 3) AT KM. 71.5, THERE IS A 200 METER STRETCH WHICH IS HEAVILY POTHOLED.

5. BRIDGES: THERE IS A SINGLE LANE BAILEY BRIDGE ABOUT 10 METERS LONG LOCATED 41.5 KILOMETERS FROM KIGALI. IT IS IN GOOD CONDITION AND APPEARS CAPABLE OF SUSTAINING NEAVY TRUCKS. AT THE BORDER CROSSING AT GATUNA, THERE IS A BRIDGE WHICH NEEDS TO BE REPLACED. THE BRIDGE, LOCATED IN THE AREA BETWEEN THE RWANDAN AND UGANDAN INSPECTION POSTS, WAS BLOWN UP IN 1990 AND REPLACED WITH A MAKESHIFT BRIDGE. THIS TEMPORARY BRIDGE GROANS AND SWAYS WHEN HEAVY TRUCKS CROSS IT. IT WOULD HAVE TO BE REPLACED WITH A BAILEY BRIDGE IN ORDER FOR TRUCKS TO USE THE ROAD ON A REGULAR BASIS FOR DELIVERY OF RELIEF SUPPLIES.

6. CHECKPOINTS/FORMALITIES: ONLY FOUR MILITARY CHECKPOINTS WERE ENCOUNTERED ON THE DRIVE FROM KIGALI TO  
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

Date Printed: 06/24/1998

DOC\_NUMBER: 94STATE222892

CHANNEL: n/a

2:

PAGE 04 STATE 222892 182313Z  
THE BORDER AT GATUNA, WHICH TOOK ABOUT 70 MINUTES. THERE  
IS A FIFTH MILITARY CHECKPOINT AT THE BORDER, BUT THERE  
WERE NO FORMALITIES TO EXIT RWANDA. ON THE UGANDAN SIDE  
OF THE BORDER, THE VEHICLE, DRIVER AND PASSENGERS MUST BE  
REGISTERED. IT ONLY TOOK 15 MINUTES TO COMPLETE THE WHOLE  
PROCESS. TARNOFF

LIMITED OFFICIAL USE

NNNN

\*\*\* Current Handling Restrictions \*\*\* n/a  
\*\*\* Current Classification \*\*\* LIMITED OFFICIAL USE